

“Industrial Training Report on Production, Quality Control and Maintenance Practices at Sun Engineering.”

Ankush Govind Thombare¹, Gaurav Rajendra Shahane², Dr. Ramesh Suryabhan Gadakh³

¹ Student, Department of Mechanical Engineering Sau Sundarbai Manik Adsul Polytechnic, Chas, Ahilyanagar, India

² Guide, Department of Mechanical Engineering Sau Sundarbai Manik Adsul Polytechnic, Chas, Ahilyanagar, India

³ Principal Sau Sundarbai Manik Adsul Polytechnic, Chas, Ahilyanagar, India

Abstract

Manufacturing industries depend on the effective integration of production, quality control and maintenance activities to achieve productivity, reliability and customer satisfaction. This paper presents a case study of **Sun Engineering**, with particular emphasis on its production activities, quality inspection practices and maintenance management. The study examines the relationship between production planning, manufacturing operations, inspection procedures and machine maintenance. Modern manufacturing operations require consistent process control, accurate inspection and reliable equipment to minimize rejection, downtime and production losses. Public information on Sun Engineering indicates capabilities in precision sheet-metal manufacturing, including CNC turret punching, laser cutting, CNC bending, tube processing and fabrication.

The study discusses the role of incoming material inspection, in-process inspection, final inspection, preventive maintenance, breakdown maintenance and workplace safety. The analysis indicates that coordination between production, quality and maintenance departments can improve machine availability, product consistency and overall manufacturing performance.

Keywords: Production Management, Quality Control, Maintenance, CNC Manufacturing, Preventive Maintenance, Industrial Engineering, Productivity.

1. Introduction

The manufacturing sector plays an important role in industrial development by converting raw materials into useful components and finished products. The performance of a manufacturing

organization depends on several interconnected functions, particularly **production, quality and maintenance**.

Production management deals with planning, scheduling, material utilization, machine operation and achieving production targets. Quality management ensures that manufactured components meet specified dimensions, tolerances, functional requirements and customer expectations. Maintenance management ensures that machines, tools and equipment remain available and operate safely and efficiently.

Sun Engineering is associated with engineering manufacturing activities. Its publicly available information describes precision sheet-metal processes such as CNC turret punching, laser cutting, CNC bending, pipe/tube laser cutting, guillotine cutting and fabrication.

The integration of these three functions is essential because a machine breakdown can stop production, while improper process control can increase rejection and rework. Similarly, poor maintenance can affect dimensional accuracy and product quality.

2. Objectives of the Study

The major objectives of this study are:

1. To study the production activities carried out in an engineering manufacturing environment.
2. To understand the role of production planning and machine utilization.
3. To study quality inspection procedures used during manufacturing.
4. To understand preventive and breakdown maintenance practices.
5. To identify common causes of production loss and rejection.
6. To study the relationship between production, quality and maintenance departments.
7. To suggest measures for improving productivity and reducing downtime.

8. To understand the importance of workplace safety in manufacturing operations.

3. Company and Manufacturing Overview

Sun Engineering's publicly available manufacturing information describes an integrated manufacturing approach from raw material to finished component. Its listed capabilities include:

- CNC turret punching
- CNC laser cutting
- Tube and pipe processing
- CNC bending
- Guillotine cutting
- Fabrication
- Industrial assemblies
- Material-handling components
- Electrical and control-system enclosures

The company states that its manufacturing processes are intended to provide repeatability, accuracy and production-ready output.

Typical Manufacturing Flow

Raw Material → Material Inspection → Cutting → CNC Processing → Bending → Fabrication/Assembly → Quality Inspection → Final Inspection → Packing → Dispatch

This type of process flow allows production and quality personnel to monitor the component at different stages rather than depending only on final inspection.

4. Production Department

The production department is responsible for converting raw material into finished components according to drawings, specifications and production schedules.

4.1 Production Planning

Production planning includes:

- Study of customer requirements
- Interpretation of engineering drawings
- Material planning
- Machine selection
- Process planning
- Production scheduling
- Tool and fixture planning
- Manpower allocation
- Inspection planning
- Dispatch planning

Effective production planning helps minimize machine idle time and unnecessary material movement.

4.2 Raw Material Handling

Raw materials are received according to specified grades, dimensions and quantities. Before production, material identification and basic inspection are important.

Typical checks include:

- Material grade
- Thickness
- Length and width
- Surface condition
- Quantity
- Damage or corrosion

Proper material identification reduces the possibility of using incorrect material during production.

4.3 CNC Manufacturing

CNC machines provide automated and repeatable manufacturing operations. In sheet-metal manufacturing, CNC punching and laser cutting can be used to produce accurately shaped components. Sun Engineering publicly lists CNC turret punching and laser cutting among its manufacturing capabilities.

The basic CNC production sequence is:

Drawing → CAD/CAM Program → Machine Setup → Tool Selection → Trial Component → Inspection → Batch Production

4.4 Bending Operation

CNC bending is used to produce required angles and geometries.

Important parameters include:

- Material thickness
- Bend angle
- Bend allowance
- Tool selection
- Die opening
- Spring-back
- Component dimensions

Improper bending parameters can result in dimensional errors and rejection.

4.5 Fabrication

Fabrication may involve:

- Cutting
- Bending
- Welding
- Drilling
- Grinding
- Assembly
- Finishing

The sequence depends on the component design and customer requirements.

5. Quality Control Department

Quality control is responsible for ensuring that products conform to drawings, specifications and applicable requirements.

Quality activities should be performed at different stages rather than only after production is completed.

5.1 Incoming Quality Inspection

Incoming material can be inspected for:

- Dimensions
- Thickness
- Surface condition
- Material identification
- Quantity
- Visual defects

5.2 In-Process Inspection

During manufacturing, inspectors or operators can check:

- Component dimensions
- Hole diameter
- Hole position
- Bend angle
- Flatness
- Surface condition
- Weld quality
- Assembly dimensions

In-process inspection helps identify defects before large quantities of components are produced.

5.3 Final Inspection

Final inspection may include:

- Dimensional inspection
- Visual inspection
- Functional inspection
- Surface-finish inspection
- Assembly inspection
- Drawing/specification verification

A quality-control approach that monitors the production process rather than relying only on final inspection can help identify defects earlier.

6. Quality Improvement Techniques

Several quality tools can be applied in an engineering manufacturing organization.

6.1 Check Sheet

Used for recording the frequency and type of defects.

6.2 Pareto Analysis

Used to identify the major causes responsible for a large proportion of defects.

6.3 Cause-and-Effect Diagram

Also called the **Ishikawa or Fishbone Diagram**. It can classify causes under:

- Man
- Machine
- Material
- Method
- Measurement
- Environment

6.4 5 Why Analysis

The 5 Why technique is useful for identifying the root cause of repeated defects or machine failures.

6.5 Statistical Process Control

Control charts can be used to monitor process variation and identify abnormal process behavior.

Research on manufacturing quality maintenance also identifies tools such as process capability analysis, Pareto diagrams, check sheets and control charts as useful approaches for improving quality.

7. Maintenance Department

Maintenance plays an important role in ensuring continuous production.

The major objectives of maintenance are:

- Reduce machine breakdowns
- Increase machine availability
- Improve equipment reliability
- Reduce production losses
- Maintain machine accuracy
- Improve workplace safety
- Extend machine life

Maintenance is closely related to production and product quality. Manufacturing research notes that maintenance strategies influence productivity, reliability, safety and product quality.

8. Types of Maintenance

8.1 Preventive Maintenance

Preventive maintenance is carried out at predetermined intervals to reduce the probability of equipment failure.

Typical activities include:

- Lubrication
- Cleaning
- Inspection
- Belt inspection

- Electrical connection inspection
- Hydraulic-system inspection
- Pneumatic-system inspection
- Tool inspection
- Replacement of worn components

Preventive maintenance can reduce unplanned downtime and production interruptions.

8.2 Breakdown Maintenance

Breakdown maintenance is performed after equipment failure.

Typical procedure:

Machine Failure → Diagnosis → Root Cause Identification → Repair → Trial Run → Quality Verification → Production Restart

Although breakdown maintenance is necessary in some situations, excessive dependence on it can cause unplanned production interruptions.

8.3 Predictive Maintenance

Predictive maintenance uses equipment-condition information to identify potential failures before they become major problems.

Possible parameters include:

- Vibration
- Temperature
- Noise
- Lubricant condition
- Motor current
- Hydraulic pressure

Condition-based and predictive maintenance approaches can support improved equipment reliability and reduce unnecessary maintenance activities.

9. Relationship Between Production, Quality and Maintenance

The three departments are strongly interconnected.

Department	Main Responsibility	Major Performance Indicator
Production	Manufacture components according to schedule	Production output
Quality	Ensure product conformity	Rejection/rework
Maintenance	Maintain machine availability	Downtime/MTBF
Production + Quality	Stable manufacturing process	First-pass yield
Production + Maintenance	Reliable	Machine

Department	Main Responsibility	Major Performance Indicator
Maintenance	equipment	availability
Quality	+ Accurate machine condition	Defect reduction

For example, if a CNC machine develops excessive backlash, the resulting dimensional variation may cause component rejection. Therefore, the quality department may identify the problem while the maintenance department investigates the machine condition.

10. Common Production Problems

Typical problems that may occur in engineering manufacturing include:

1. Machine breakdown
2. Tool wear
3. Improper machine setup
4. Incorrect CNC program
5. Material variation
6. Dimensional errors
7. Excessive rejection
8. Rework
9. Production delays
10. Improper material handling
11. Lack of preventive maintenance
12. Inadequate inspection

11. Suggested Improvement Measures

The following measures can improve manufacturing performance:

Production

- Improve production scheduling.
- Reduce machine setup time.
- Standardize work instructions.
- Improve material flow.
- Monitor machine utilization.
- Use appropriate tools and fixtures.

Quality

- Increase in-process inspection.
- Maintain calibrated measuring instruments.
- Record rejection data.
- Use Pareto analysis for recurring defects.
- Implement root-cause analysis.
- Maintain inspection records.

Maintenance

- Prepare machine-wise preventive-maintenance schedules.
- Maintain machine history cards.
- Record breakdown duration.
- Monitor MTBF and MTTR.
- Maintain critical spare parts.
- Introduce condition monitoring where practical.

12. Key Performance Indicators

The following KPIs can be used to evaluate the manufacturing system:

Production Efficiency

$$\text{Production Efficiency} = \frac{\text{Actual Output}}{\text{Planned Output}} \times 100$$

Rejection Percentage

$$\text{Rejection Percentage} = \frac{\text{Rejected Components}}{\text{Total Components}} \times 100$$

Machine Availability

$$\text{Availability} = \frac{\text{Available Production Time}}{\text{Planned Production Time}} \times 100$$

MTBF

$$\text{MTBF} = \frac{\text{Total Operating Time}}{\text{Number of Failures}}$$

MTTR

$$\text{MTTR} = \frac{\text{Total Repair Time}}{\text{Number of Repairs}}$$

These indicators can be monitored periodically to identify improvement opportunities.

13. Results and Discussion

The study shows that production performance cannot be considered independently from quality and maintenance. A stable manufacturing process requires:

Reliable Machine + Correct Material + Proper Process + Skilled Operator + Effective Inspection = Consistent Product Quality

Similarly:

Preventive Maintenance → Reduced Breakdown → Increased Availability → Improved Production → Reduced Delivery Delay

Quality inspection also provides useful information to production and maintenance teams. Repeated dimensional defects may indicate incorrect machine settings, tool wear or machine-condition problems.

Modern manufacturing research emphasizes the importance of diagnostic and prognostic approaches for improving equipment performance, reliability and maintainability.

14. Conclusion

This paper presents a case study framework for studying **production, quality control and maintenance activities at Sun Engineering**. Production activities such as CNC processing, cutting, bending and fabrication require systematic planning and process control. Quality inspection at incoming, in-process and final stages helps identify defects and maintain product conformity. Maintenance activities, particularly preventive maintenance, help improve machine availability and reduce unexpected production interruptions. The integration of production, quality and maintenance departments is therefore essential for achieving higher productivity, consistent quality, reduced rejection and reliable delivery. A data-driven approach using production output, rejection percentage, machine availability, MTBF and MTTR can further support continuous improvement.

15. References

1. Sun Engineering, **Manufacturing Capabilities and Company Information**, Sun Engineering, Coimbatore.
2. Vogl, G. W., Weiss, B. A., & Donmez, M. A., "A Review of Diagnostic and Prognostic Capabilities and Best Practices for Manufacturing," *Journal of Intelligent Manufacturing*, 2019.
3. "Evolving the Indigenous TPM Methodology for the Indian Manufacturing Industry," research literature on Total Productive Maintenance and quality maintenance.
4. "Maintenance Practices in Indian Manufacturing Industries," research literature on maintenance strategies and their relationship with productivity, quality and reliability.
5. Production Management reference material covering preventive-maintenance inspection and its effect on downtime, repairs and quality control.